

## Certificate of Structural Repair

PRC Repair Specification:  
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0102

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**2 Capgrave Close  
Brislington  
Bristol  
BS4 4TJ**



## Schedule

Alan Cairns

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

29 December 2020

Contract Completion Date

076

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

11 June 2021

Issue date



**PRC Repair Specification:**  
**BSF-Reema-1:2014**  
**Certificate No. PRC - 0102**  
**Schedule Continued:**

**Certificate of Structural Repair**

Contract premises:  
**2 Capgrave Close**  
**Brislington**  
**Bristol**  
**BS4 4TJ**

**076**  
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location
N/A	
N/A	

**Notes:**  
 Click here to enter text.

Alan Cairns  
Name, Position



Signature

Alan Cairns  
Registered Practitioner Company Name

**11 June 2021**  
Issue date

