

Certificate of Structural Repair

PRC Repair Specification:
BSF_RS_Airey:2017

Requirements for repair of Airey House

Certificate No. PRC - 0104

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**3 Windmill Fields
East Worldham
Alton
GU34 3AR**



Schedule

Alan Cairns

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF_RS_Airey:2017 in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF_RS_Airey:2017: "Requirements for repair of Airey House".

22 July 2021

Contract Completion Date

078

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

20 September 2021

Issue date



PRC Repair Specification:
BSF_RS_Airey:2017
Certificate No. PRC - 0104
Schedule Continued:

Certificate of Structural Repair

Contract premises:

**3 Windmill Fields
East Worldham
Alton
GU34 3AR**

078

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF_RS_Airey:2017, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

20 September 2021

Issue date

