

## Certificate of Structural Repair

PRC Repair Specification:  
BSF-Reema-1:2014

Requirements for repair of Reema House

**Certificate No. PRC - 0106**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**60 Kenwood Road  
Fareham  
PO16 9LR**



## Schedule

Alan Cairns

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

20 April 2021

Contract Completion Date

081

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

04 August 2021

Issue date



PRC Repair Specification:  
BSF-Reema-1:2014  
Certificate No. PRC - 0106  
Schedule Continued:

Certificate of Structural Repair

Contract premises:  
**60 Kenwood Road**  
**Fareham**  
**PO16 9LR**

**081**  
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns  
Name, Position



Signature

Alan Cairns  
Registered Practitioner Company Name

04 August 2021  
Issue date

