

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0107

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**146 Crosscombe Drive
Bristol
BS13 0BS**



Schedule

Alan Cairns

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

20 September 2021

Contract Completion Date

079

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

20 September 2021

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0107
Schedule Continued:

Certificate of Structural Repair

Contract premises:
146 Crosscombe Drive
Bristol
BS13 0BS

079
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns
Name, Position

Signature

Alan Cairns
Registered Practitioner Company Name

20 September 2021
Issue date

