

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0126

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**2 Farringford Road
Southampton
SO19 6PL**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

26 January 2022

Contract Completion Date

097

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

01 February 2022

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0126
Schedule Continued:

Certificate of Structural Repair

Contract premises:
2 Farringford Road
Southampton
SO19 6PL

097
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns
Name, Position

Signature

Alan Cairns Associates Ltd
Registered Practitioner Company Name

01 February 2022
Issue date

