

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0127

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**130 Porlock Road
Southampton
SO16 9JF**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

04 March 2022

Contract Completion Date

103

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

10 March 2022

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0127
Schedule Continued:

Certificate of Structural Repair

Contract premises:
130 Porlock Road
Southampton
SO16 9JF

103
Contract Number

| Scope of Works | Location |
|---|---|
| This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken. | 130 Porlock Road Southampton SO16 9JF |

| Works not completed or excluded | Location |
|---------------------------------------|----------|
| Single storey side extension excluded | As above |
| | |

Notes:

Alan Cairns
Name, Position



Signature

Alan Cairns Associates Ltd
Registered Practitioner Company Name

10 March 2022
Issue date

