

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0130

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**31 Gassons Road
Lechlade
Gloucestershire
GL7 3BQ**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

09 September 2022

Contract Completion Date

102

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

15 September 2022

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0130

Certificate of Structural Repair

Schedule Continued:

Contract premises:
31 Gassons Road
Lechlade
Gloucestershire
GL7 3BQ

102
 Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	31 Gassons Road Lechlade Gloucestershire GL7 3BQ

Works not completed or excluded	Location
Front porch excluded	As above
Single storey rear extension excluded	As above

Notes:

Alan Cairns
 Name, Position



Signature

Alan Cairns Associates Ltd
 Registered Practitioner Company Name

15 September 2022
 Issue date

