

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0136

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**81 Meadowcroft
Swindon
Wiltshire
SN2 7LA**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

06 March 2023

Contract Completion Date

109

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

13 March 2023

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0136
Schedule Continued:

Certificate of Structural Repair

Contract premises:
81 Meadowcroft
Swindon
Wiltshire
SN2 7LA

109
 Contract Number

| Scope of Works | Location |
|---|---|
| This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken. | 81 Meadowcroft Swindon Wiltshire SN2 7LA |

| Works not completed or excluded | Location |
|---|----------|
| Two-storey side extension excluded | As above |
| Rendering of blockwork on the side of the property not carried out due to extension | As above |

Notes:

Alan Cairns
 Name, Position



Signature

Alan Cairns Associates Ltd
 Registered Practitioner Company Name

13 March 2023
 Issue date

