

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0137

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**33 Marsh Avenue
Dronfield
Derbyshire
S18 2HB**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

21 March 2023

Contract Completion Date

111

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

27 March 2023

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0137
Schedule Continued:

Certificate of Structural Repair

Contract premises:
33 Marsh Avenue
Dronfield
Derbyshire
S18 2HB

111
 Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	33 Marsh Avenue Dronfield Derbyshire S18 2HB

Works not completed or excluded	Location
Rear conservatory excluded	As above

Notes:

Alan Cairns
 Name, Position



Signature

Alan Cairns Associates Ltd
 Registered Practitioner Company Name

27 March 2023
 Issue date

