

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0138

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**23 The Valley
Salisbury
Wiltshire
SP2 9EJ**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

31 March 2023

Contract Completion Date

114

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

05 April 2023

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0138
Schedule Continued:

Certificate of Structural Repair

Contract premises:

23 The Valley
Salisbury
Wiltshire
SP2 9EJ

114

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	23 The Valley Salisbury Wiltshire SP2 9EJ

Works not completed or excluded	Location
Side single storey outbuilding and covered passageway are excluded	As above

Notes:

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

05 April 2023

Issue date

