

Certificate of Structural Repair

PRC Repair Specification:
BSF-Reema-1:2014

Requirements for repair of Reema House

Certificate No. PRC - 0140

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**10 Perran Road
Southampton
Hampshire
SO16 9HN**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

08 August 2023

Contract Completion Date

118

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

14 August 2023

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0140
Schedule Continued:

Certificate of Structural Repair

Contract premises:

10 Perran Road
Southampton
Hampshire
SO16 9HN

118

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	10 Perran Road Southampton Hampshire SO16 9HN

Works not completed or excluded	Location
Front porch excluded	As above

Notes:

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

14 August 2023

Issue date

