

Certificate of Structural Repair

**PRC Repair Specification:
BSF-Reema-1:2014**

Requirements for repair of Reema House

Certificate No. PRC - 0141

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**28 Furze Road
Tadley
Hampshire
RG26 4QX**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

22 September 2023

Contract Completion Date

116

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

25 September 2023

Issue date



PRC Repair Specification:
BSF-Reema-1:2014
Certificate No. PRC - 0141

Certificate of Structural Repair

Schedule Continued:

Contract premises:

**28 Furze Road
Tadley
Hampshire
RG26 4QX**

116

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	28 Furze Road Tadley Hampshire RG26 4QX

Works not completed or excluded	Location
Front porch excluded	As above
Side single storey outbuilding and covered passageway are excluded	As above

Notes:

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

25 September 2023

Issue date

