

Certificate of Structural Repair

PRC Repair Specification:
2017:BSF_RS_Airey

Requirements for repair of Airey House

Certificate No. PRC - 0084

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**9 Sherston Close
Fishponds
Bristol
BS16 2LP**



Schedule

Alan Cairns

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2017:BSF_RS_Airey in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification 2017:BSF_RS_Airey: "Requirements for repair of Airey House".

25 November 2020

Contract Completion Date

BSF 022

Contract Number

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

15 December 2020

Issue date



PRC Repair Specification:
2017:BSF_RS_Airey
Certificate No. PRC - 0084
Schedule Continued:

Certificate of Structural Repair

Contract premises:
9 Sherston Close
Fishponds
Bristol
BS16 2LP

BSF 022
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2017:BSF_RS_Airey, against which the repair was undertaken.	

Works not completed or excluded	Location
N/A	
N/A	

Notes:
 Click here to enter text.

Alan Cairns
Name, Position



Signature

Alan Cairns
Registered Practitioner Company Name

15 December 2020
Issue date

