

# Certificate of Structural Repair

PRC Repair Specification:  
2014: BSF, Reema, 01

Requirements for repair of Reema House

Certificate No. PRC - 0100

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**47 Crosscombe Drive,  
Hartcliffe,  
Bristol,  
BS13 0DE**



## Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014: BSF, Reema, 01 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification 2014: BSF, Reema, 01: "Requirements for repair of Reema House".

09 October 2020

Contract Completion Date

074

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

30 October 2020

Issue date



**PRC Repair Specification:**  
 2014: BSF, Reema, 01  
**Certificate No. PRC - 0100**  
**Schedule Continued:**

**Certificate of Structural Repair**

Contract premises:  
**47 Crosscombe Drive,**  
**Hartcliffe,**  
**Bristol,**  
**BS13 0DE**

074  
 Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014: BSF, Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location
N/A	
N/A	

**Notes:**  
 Click here to enter text.

Alan Cairns  
 Name, Position



Signature

Alan Cairns  
 Registered Practitioner Company Name

30 October 2020  
 Issue date

