

Certificate of Structural Repair

PRC Repair Specification:

[2014,BSF,Reema,01]

Requirements for repair of Reema House Type

Certificate No. [PRC - 00001]

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule for the following premises:

**33 Chambers Avenue
Romsey
Hampshire
SO51 5BG**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014,BSF,Reema,01 in respect of the repair of Reema House Type, do certify that the repair was carried out in accordance with PRC Repair Specification 2014,BSF,Reema,01: "Requirements for repair of Reema House Type".

[20 November 2015]

Contract Completion Date

[0001]

Contract Number

[Mr Alan Cairns]

Name, Position

Signature

[Alan Cairns Associates Ltd]

Registered Practitioner Company Name

[19 July 2016]

Issue date



PRC Repair Specification: 2014,BSF,Reema,01
Repair
Certificate No. PRC - 00001

Certificate of Structural

Schedule Continued:

Contract premises:

33 Chambers Avenue
Romsey
Hampshire
SO51 5BG

0001

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014,BSF,Reema,01, against which the repair was undertaken.	33 Chambers Avenue Romsey Hampshire SO51 5BG

Works not completed or excluded	Location
None	Not appropriate

Notes:

[N/A]

Mr Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

19 July 2016

Issue date

