

Certificate of Structural Repair

PRC Repair Specification:

[2014,BSF,Reema,01]

Requirements for repair of Reema House Type

Certificate No. [PRC-00007]

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**173 Four Acres
Withywood
Bristol
BS13 8QQ**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014,BSF,Reema,01 in respect of the repair of Reema House Type, do certify that the repair was carried out in accordance with PRC Repair Specification 2014,BSF,Reema,01: "Requirements for repair of Reema House Type".

[19 April 2016]

Contract Completion Date

[0007]

Contract Number

[Mr Alan Cairns]

Name, Position

Signature

[Alan Cairns Associates Ltd]

Registered Practitioner Company Name

[15 September 2016]

Issue date



PRC Repair Specification: 2014,BSF,Reema,01
Repair

Certificate of Structural

Certificate No. PRC-00007

Schedule Continued:

Contract premises:

0007

173 Four Acres

Contract Number

Withywood

Bristol

BS13 8QQ

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014,BSF,Reema,01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

[N/A]

Mr Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

15 September 2016

Issue date

