

# Certificate of Structural Repair

PRC Repair Specification:  
2014:BSF,Reema, 01

Requirements for repair of Reema House

**Certificate No. PRC - 0062**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**40 St Marys Road,  
Tetbury,  
Gloucestershire,  
GL8 8BG**



## Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House ".

22 April 2019

Contract Completion Date

0062

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

09 July 2019

Issue date



PRC Repair Specification:  
2014:BSF,Reema, 01  
Certificate No. PRC - 0062  
Schedule Continued:

Certificate of Structural Repair

Contract premises:  
**40 St Marys Road,  
Tetbury,  
Gloucestershire,  
GL8 8BG**

0062

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	


Works not completed or excluded	Location

**Notes:**

Click here to enter text.

Brian Stocker

Name, Position



Signature

Brian Stocker

Registered Practitioner Company Name

09 July 2019

Issue date

