

Certificate of Structural Repair

PRC Repair Specification:
2017:BSF,Airey, 01

Requirements for repair of Airey House

Certificate No. PRC - 0067

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**5 Orchard Lane,
Barkston Ash,
Tadcaster,
Yorkshire,
LS24 9PN**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2017:BSF,Airey, 01 in respect of the repair of Airey House , do certify that the repair was carried out in accordance with PRC Repair Specification 2017:BSF,Airey, 01: "Requirements for repair of Airey House".

04 June 2019

Contract Completion Date

0067

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

09 July 2019

Issue date



PRC Repair Specification:
2017:BSF,Airey, 01
Certificate No. PRC - 0067
Schedule Continued:

Certificate of Structural Repair

Contract premises:
5 Orchard Lane,
Barkston Ash,
Tadcaster,
Yorkshire,
LS24 9PN


0067
 Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2017:BSF,Airey, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:
 Click here to enter text.

Brian Stocker
 Name, Position



Signature

Brian Stocker
 Registered Practitioner Company Name

09 July 2019
 Issue date

