

Certificate of Structural Repair

**PRC Repair Specification:
2014:BSF,Reema, 01**

Requirements for repair of Reema House

Certificate No. PRC - 0047

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**56 Byron Road
Thornhill
Southampton
SO19 6FQ**



Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House ".

11 April 2018

Contract Completion Date

0047

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

03 December 2019

Issue date



PRC Repair Specification:
2014:BSF,Reema, 01
Certificate No. PRC - 0047
Schedule Continued:

Certificate of Structural Repair

Contract premises:

56 Byron Road
Thornhill
Southampton
SO19 6FQ

0047

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Click here to enter text.

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

03 December 2019

Issue date

