

Certificate of Structural Repair

PRC Repair Specification:
2014:BSF,Reema, 01

Requirements for repair of Reema House

Certificate No. PRC - 0056

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**48 Byron Road
Southampton
SO19 6FQ**



Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House ".

24 September 2018

Contract Completion Date

0056

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

04 December 2019

Issue date



PRC Repair Specification:
2014:BSF,Reema, 01
Certificate No. PRC - 0056
Schedule Continued:

Certificate of Structural Repair

Contract premises:

**48 Byron Road
Southampton
SO19 6FQ**

0056

Contract Number

| Scope of Works | Location |
|---|----------|
| This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken. | |

| Works not completed or excluded | Location |
|---------------------------------|----------|
| | |
| | |

Notes:

Click here to enter text.

Alan Cairns

Name, Position



Signature

Alan Cairns

Registered Practitioner Company Name

04 December 2019

Issue date

