

Certificate of Structural Repair

PRC Repair Specification:
2014:BSF, Reema, 01

Requirements for repair of a Reema House

Certificate No. PRC - 0085

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**41 The Rosary
Royal Wootton Bassett
Wiltshire
SN4 8AG**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF, Reema, 01 in respect of the repair of a Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF, Reema, 01: "Requirements for repair of a Reema House " .

26 March 2020

Contract Completion Date

0085

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

31 March 2020

Issue date



PRC Repair Specification:
2014:BSF, Reema, 01
Certificate No. PRC - 0085
Schedule Continued:

Certificate of Structural Repair

Contract premises:
41 The Rosary
Royal Wootton Bassett
Wiltshire
SN4 8AG

0085

Contract Number


Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF, Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Brian Stocker

Name, Position



Signature

Brian Stocker

Registered Practitioner Company Name

31 March 2020

Issue date

