

Certificate of Structural Repair

PRC Repair Specification:
2017:BSF, Airey, 01

Requirements for repair of Airey House

Certificate No. PRC - 0086

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**74 Mankley Road
Leonard Stanley
Stonehouse
GL10 3LY**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2017:BSF, Airey, 01 in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification 2017:BSF, Airey, 01: "Requirements for repair of Airey House".

23 March 2020

Contract Completion Date

0086

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

25 March 2020

Issue date



PRC Repair Specification:
 2017:BSF, Airey, 01
Certificate No. PRC - 0086
 Schedule Continued:

Certificate of Structural Repair

Contract premises:
74 Mankley Road
Leonard Stanley
Stonehouse
GL10 3LY


0086
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2017:BSF, Airey, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Brian Stocker
Name, Position



Signature

Brian Stocker
Registered Practitioner Company Name

25 March 2020
Issue date

