

# Certificate of Structural Repair

PRC Repair Specification:  
BSF\_RS\_Airey:2017

Requirements for repair of Airey House

**Certificate No. PRC - 0109**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**18 Carlton Road  
Sutton on Derwent  
York  
YO41 4BS**



## Schedule

Alan Cairns

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF\_RS\_Airey:2017 in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF\_RS\_Airey:2017: "Requirements for repair of Airey House".

23 July 2021

Contract Completion Date

083

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

28 September 2021

Issue date



PRC Repair Specification:  
BSF\_RS\_Airey:2017  
Certificate No. PRC - 0109  
Schedule Continued:

Certificate of Structural Repair

Contract premises:  
**18 Carlton Road**  
**Sutton on Derwent**  
**York**  
**YO41 4BS**

**083**  
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF_RS_Airey:2017, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns  
Name, Position

Signature

Alan Cairns  
Registered Practitioner Company Name

28 September 2021  
Issue date

