

Certificate of Structural Repair

PRC Repair Specification:
BSF_RS_Airey:2017

Requirements for repair of Airey House

Certificate No. PRC - 0120

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**4 St. Margarets Villas
Collier Street
Tonbridge
TN12 9SA**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF_RS_Airey:2017 in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF_RS_Airey:2017: "Requirements for repair of Airey House".

17 December 2021

Contract Completion Date

091

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

09 January 2022

Issue date



PRC Repair Specification:
BSF_RS_Airey:2017
Certificate No. PRC - 0120
Schedule Continued:

Certificate of Structural Repair

Contract premises:
**4 St. Margarets Villas
Collier Street
Tonbridge
TN12 9SA**

091
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF_RS_Airey:2017, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns
Name, Position

Signature

Alan Cairns Associates Ltd
Registered Practitioner Company Name

09 January 2022
Issue date

