

Certificate of Structural Repair

PRC Repair Specification:
BSF_RS_Airey:2017

Requirements for repair of Airey House

Certificate No. PRC - 0144

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**8 Common Lane
Cutthorpe
Chesterfield
Derbyshire
S42 7AN**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF_RS_Airey:2017 in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF_RS_Airey:2017: "Requirements for repair of Airey House".

03 November 2023

Contract Completion Date

117

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

12 November 2023

Issue date



PRC Repair Specification:
BSF_RS_Airey:2017
Certificate No. PRC - 0144
Schedule Continued:

Certificate of Structural Repair

Contract premises:

8 Common Lane
Cutthorpe
Chesterfield
Derbyshire
S42 7AN

117

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF_RS_Airey:2017, against which the repair was undertaken.	8 Common Lane Cutthorpe Chesterfield Derbyshire S42 7AN

Works not completed or excluded	Location
2-storey side extension excluded	As above

Notes:

Alan Cairns

Name, Position



Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

12 November 2023

Issue date

