bre

Certificate of Structural I	Repair <u>CER</u>
PRC Repair Specification: BSF_RS_Airey:2017	
Requirements for repair of Airey House	U
Certificate No. PRC - 0146	
This certificate is issued by the BRE Global Registered P named in (1) of the schedule, for the client in (2) of the following premises:	
33 Tower View Rowde Devizes Wiltshire SN10 2PR	
Schedule	
Alan Cairns Associates Ltd	0001/X-01 Practitioner Certificate No.
I, being certified to PRC Repair Specification BSF_RS_Airey:2017 in respect of the repair of Airey House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF_RS_Airey:2017: "Requirements for repair of Airey House".	
21 February 2024	123
Contract Completion Date	Contract Number
Alan Cairns	Alle Can
Name, Position	Signature
Alan Cairns Associates Ltd	23 February 2024
Registered Practitioner Company Name	Issue date
BAL CERTIFICATION	

Practitioner Certificate No. 0001/X-01

bre

PRC Repair Specification: BSF_RS_Airey:2017 Certificate No. PRC - 0146

Schedule Continued:

 Contract premises:
 123

 33 Tower View
 Contract Number

 Rowde
 Envizes

 Wiltshire
 View

Certificate of Structural Repair

Scope of WorksLocationThis certificate covers only the work detailed in
the PRC Repair Specification33 Tower ViewBSF_RS_Airey:2017, against which the repair
was undertaken.DevizesWiltshire
SN10 2PR

Works not completed or excluded	Location

Notes:

SN10 2PR

Alan Cairns

Name, Position

Alan Cairns Associates Ltd Registered Practitioner Company Name 23 February 2024

Alle Can

Issue date

Signature



Practitioner Certificate No. 0001/X-01