

Certificate of Structural Repair

**PRC Repair Specification:
2014:BSF, Reema, 01**

Requirements for repair of Reema House

Certificate No. PRC - 0081

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**29 Pinnock's Place
Upper Stratton
Swindon
SN2 7NE**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF, Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF, Reema, 01: "Requirements for repair of Reema House".

04 October 2019

Contract Completion Date

019

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

08 June 2020

Issue date



PRC Repair Specification:
2014:BSF, Reema, 01
Certificate No. PRC - 0081

Certificate of Structural Repair

Schedule Continued:

Contract premises:
29 Pinnock's Place
Upper Stratton
Swindon
SN2 7NE


019
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF, Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:
Click here to enter text.

Brian Stocker
Name, Position



Signature

Brian Stocker
Registered Practitioner Company Name

08 June 2020
Issue date

