

# Certificate of Structural Repair

**PRC Repair Specification:  
BSF-Reema-1:2014**

Requirements for repair of Reema House

**Certificate No. PRC - 0118**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**3 Kingsclere Avenue  
Southampton  
SO19 9LB**



## Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification BSF-Reema-1:2014 in respect of the repair of Reema House, do certify that the repair was carried out in accordance with PRC Repair Specification BSF-Reema-1:2014: "Requirements for repair of Reema House".

16 December 2021

Contract Completion Date

089

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns Associates Ltd

Registered Practitioner Company Name

17 December 2021

Issue date



PRC Repair Specification:  
BSF-Reema-1:2014  
Certificate No. PRC - 0118  
Schedule Continued:

Certificate of Structural Repair

Contract premises:  
**3 Kingsclere Avenue**  
**Southampton**  
**SO19 9LB**

**089**  
Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification BSF-Reema-1:2014, against which the repair was undertaken.	

Works not completed or excluded	Location

Notes:

Alan Cairns  
Name, Position



Signature

Alan Cairns Associates Ltd  
Registered Practitioner Company Name

17 December 2021  
Issue date

