bre

0001/X-01

Certificate of Structura	l Repair
PRC Repair Specification: BSF-Reema-1:2014	
Requirements for repair of Reema House	U J
Certificate No. PRC - 0135	
This certificate is issued by the BRE Global Register named in (1) of the schedule, for the client in (2) of following premises:	
26 Hawkley Green Southampton Hampshire SO19 9NQ	
Schedule	
Alan Cairns Associates Ltd 1) Issuing Practitioner	0001/X-01 Practitioner Certificate No.
I, being certified to PRC Repair Specification BSF-Reema	-1:2014 in respect of the repair of Reema House , do certify that the ecification BSF-Reema-1:2014: "Requirements for repair of Reema
15 February 2023	112
Contract Completion Date	Contract Number
Alan Cairns Name, Position	Signature
Alan Cairns Associates Ltd	28 February 2023
Registered Practitioner Company Name	Issue date
Practitioner Certificate No.	BF1339 Rev. 0.3

Page 1 of 2

© BRE Global Limited, 2019

bre

PRC Repair Specification: BSF-Reema-1:2014 Certificate No. PRC - 0135	Certificate of Structural Repair
Schedule Continued:	
Contract premises:	112 Contract Number
26 Hawkley Green	
Southampton	
Hampshire	
SO19 9NQ	

Scope of Works	Location
This certificate covers only the work detailed in	26 Hawkley Green
the PRC Repair Specification BSF-Reema-1:2014,	Southampton
against which the repair was undertaken.	Hampshire
	SO19 9NQ

Location

Notes:

the law

Alan Cairns Name, Position

Alan Cairns Associates Ltd

Registered Practitioner Company Name

28 February 2023

Issue date

Signature



Practitioner Certificate No. 0001/X-01