

Certificate of Structural Repair

PRC Repair Specification:

[2014,BSF,Reema,01]

Requirements for repair of Reema House Type

Certificate No. [PRC - 00012]

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**37 Windmill Piece
Chiseldon
Swindon
SN4 0NY**



Schedule

Alan Cairns Associates Ltd

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014,BSF,Reema,01 in respect of the repair of Reema House Type, do certify that the repair was carried out in accordance with PRC Repair Specification 2014,BSF,Reema,01: "Requirements for repair of Reema House Type".

[02 November 2016]

Contract Completion Date

[0012]

Contract Number

[Mr Alan Cairns]

Name, Position

Signature

[Alan Cairns Associates Ltd]

Registered Practitioner Company Name

[09 January 2017]

Issue date



PRC Repair Specification: 2014,BSF,Reema,01
Repair Certificate No. PRC - 00012

Certificate of Structural

Schedule Continued:

Contract premises:	0012
37 Windmill Piece	<small>Contract Number</small>
Chiseldon	
Swindon	
SN4 0NY	

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014,BSF,Reema,01, against which the repair was undertaken.	[]

Works not completed or excluded	Location
[]	[]
[]	[]

Notes:

[N/A]

Mr Alan Cairns
Name, Position

Signature

Alan Cairns Associates Ltd
Registered Practitioner Company Name

09 January 2017
Issue date

