

# Certificate of Structural Repair

**PRC Repair Specification:  
2014:BSF,Reema, 01**

Requirements for repair of Reema House

**Certificate No. PRC - 0077**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**78 Buttington Road  
Sedbury  
Chepstow  
NP16 7AN**



## Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House".

28 June 2019

Contract Completion Date

0077

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

26 September 2019

Issue date



**PRC Repair Specification:**  
 2014:BSF,Reema, 01  
**Certificate No. PRC - 0077**  
**Schedule Continued:**

**Certificate of Structural Repair**

**Contract premises:**  
**78 Buttington Road**  
**Sedbury**  
**Chepstow**  
**NP16 7AN**


**0077**  
 Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

**Notes:**  
 Click here to enter text.

**Brian Stocker**  
 Name, Position



Signature

**Brian Stocker**  
 Registered Practitioner Company Name

**26 September 2019**  
 Issue date

