

# Certificate of Structural Repair

PRC Repair Specification:  
2014:BSF,Reema, 01

Requirements for repair of Reema House

**Certificate No. PRC – 0052**

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**4 Mardale Road,  
Southampton,  
SO16 9GT**



## Schedule

Alan Cairns

1) Issuing Practitioner

PRC-0001/X-01

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House ".

03 September 2018

Contract Completion Date

0052

Contract Number

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

04 December 2019

Issue date



**PRC Repair Specification:**  
2014:BSF,Reema, 01  
**Certificate No. PRC – 0052**  
**Schedule Continued:**

**Certificate of Structural Repair**

Contract premises:

**4 Mardale Road,  
Southampton,  
SO16 9GT**

0052

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	

Works not completed or excluded	Location

**Notes:**

Click here to enter text.

Alan Cairns

Name, Position

Signature

Alan Cairns

Registered Practitioner Company Name

04 December 2019

Issue date

