

Certificate of Structural Repair

PRC Repair Specification:
2014:BSF,Reema, 01

Requirements for repair of Reema House

Certificate No. PRC - 0078

This certificate is issued by the BRE Global Registered Practitioner named in (1) of the schedule, for the client in (2) of the schedule for the following premises:

**8 Cadland Park
Holbury
Southampton
SO45 2PE**



Schedule

Brian Stocker

1) Issuing Practitioner

PRC-0001

Practitioner Certificate No.

I, being certified to PRC Repair Specification 2014:BSF,Reema, 01 in respect of the repair of Reema House , do certify that the repair was carried out in accordance with PRC Repair Specification 2014:BSF,Reema, 01: "Requirements for repair of Reema House".

07 April 2020

Contract Completion Date

017

Contract Number

Brian Stocker

Name, Position

Signature

Brian Stocker

Registered Practitioner Company Name

28 April 2020

Issue date



PRC Repair Specification:
2014:BSF,Reema, 01
Certificate No. PRC - 0078
Schedule Continued:

Certificate of Structural Repair

Contract premises:

**8 Cadland Park
Holbury
Southampton
SO45 2PE**

017

Contract Number

Scope of Works	Location
This certificate covers only the work detailed in the PRC Repair Specification 2014:BSF,Reema, 01, against which the repair was undertaken.	


Works not completed or excluded	Location

Notes:

[Click here to enter text.](#)

Brian Stocker

Name, Position



Signature

Brian Stocker

Registered Practitioner Company Name

28 April 2020

Issue date

